

United States
Environmental Protection
Agency
Washington DC 20460

Please type or print in ink. If you need additional space, use separate sheets of paper. Indicate the letter of the item which applies.

81 04 29 OH #2

APR 29 1981

045-000-001-329

City Warren State Ohio Zip Code 44485

City Warren County Trumbull State Ohio Zip Code 44485

Phone 216 - 841-6189

US EPA RECORDS CENTER REGION 5



54649

From (Year) 1953 To (Year) ~~Present~~ 1981

[illegible]

000007 APR 29 81

Notification of Hazardous Waste Site**Side Two****F Waste Quantity:**

Place an X in the appropriate boxes to indicate the facility types found at the site.

In the "total facility waste amount" space give the estimated combined quantity (volume) of hazardous wastes at the site using cubic feet or gallons.

In the "total facility area" space, give the estimated area size which the facilities occupy using square feet or acres.

Facility Type

1. ☒ Piles
2. ☐ Land Treatment
3. ☐ Landfill
4. ☐ Tanks
5. ☒ Impoundment
6. ☐ Underground Injection
7. ☐ Drums, Above Ground
8. ☐ Drums, Below Ground
9. ☐ Other (Specify) _____

Total Facility Waste Amount

cubic feet 350,000 ft³ (estimate)

gallons _____

Total Facility Area

square feet 300,000 ft.² (estimate)

acres _____

G Known, Suspected or Likely Releases to the Environment:

Place an X in the appropriate boxes to indicate any known, suspected, or likely releases of wastes to the environment.

☐ Known ☐ Suspected ☐ Likely ☒ None

Note: Items H and I are optional. Completing these items will assist EPA and State and local governments in locating and assessing hazardous waste sites. Although completing the items is not required, you are encouraged to do so.

H Sketch Map of Site Location: (Optional)

Sketch a map showing streets, highways, routes or other prominent landmarks near the site. Place an X on the map to indicate the site location. Draw an arrow showing the direction north. You may substitute a publishing map showing the site location.

See Attached Location Map

I Description of Site: (Optional)

Describe the history and present conditions of the site. Give directions to the site and describe any nearby wells, springs, lakes, or housing. Include such information as how waste was disposed and where the waste came from. Provide any other information or comments which may help describe the site conditions.

- (K063) Sludges from lime treatment of spent pickle liquor from steel finishing operations in surface impoundments.
- (F006) Waste water treatment sludges from electro plating operations in waste pile.

002

J Signature and Title:

The person or authorized representative (such as plant managers, superintendents, trustees or attorneys) of persons required to notify must sign the form and provide a mailing address (if different than address in item A). For other persons providing notification, the signature is optional. Check the boxes which best describe the relationship to the site of the person required to notify. If you are not required to notify check "Other".

Name _____

Street _____

City _____

State _____

Zip Code _____

Signature _____

Date

Vice President of Operations

- ☐ Owner, Present
☐ Owner, Past
☐ Transporter
☐ Operator, Present
☐ Operator, Past
☐ Other

4-27-81

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

WARREN QUADRANGLE
7.5 MINUTE SERIES (TOPOGRAPHIC)
NE 1/4 WARREN 15' QUADRANGLE
N 4107.5 - W 8045/7.5

STATE OF OHIO
DEPARTMENT OF HIGHWAYS
DEPARTMENT OF NATURAL RESOURCE
DIVISION OF GEOLOGICAL SURVEY

80°52'30"
15'

511000m E

512

PARKMAN 15 MI.
6.4 MI. TO OHIO 534 513

50


BRISTOLVILLE 10 MI.
CHAMPION 4.3 MI.

R. 4 W.

4866 IV SE
(CHAMPION)

516

R. 3 W.



LOCATION MAP
THOMAS STEEL STRIP CORP.
WARREN, OHIO

SCALE 1:24000

0°07'
2 MILES